## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	6/8/2015	Time:	11:23 AM
Name of School Address of School	Corporation: ool Corporation:		RN SCHOOL COF	RP.	Corp ID:	343470
City:	Kokomo	Zip:	46901		County Number:	34
VIN:	1T88T3C2881291537		License Number:	21693	Bus Number:	25
Make of Body:	Thomas Built Buses, Inc.	Year: 2008	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2008
Bus Type:	D		Mileage:	87943		
Inspection Status:	R	Inspected By:	Randy McPike		PE:	7018

## Violations - Rejected

Inspection Code	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
91-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
68-1-1	Washers do not function properly in any manner

## **Violations - Out of Service**

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.