## REPORT OF SCHOOL BUS INSPECTION

Type of 11:10 Time: Annual Date: 6/10/2015 Inspection: AM Name of School Corporation: CULVER COMMUNITY SCHOOLS CORP. Corp ID: 505455 **Address of School Corporation:** PO Box 231 County City: Culver Zip: 46511 50 Number: License VIN: 4DRBUAFP06A236027 2475 **Bus Number:** 23 Number: Make of IC Blue Bird Make of Body: Year: 2006 2006 Year: Corporation Corporation Chassis: **Bus Type:** С Mileage: 130033 Inspection Inspected R PE: Travis Harrold 8022 Status: By:

**Violations - Rejected** 

<u>Inspection Code</u> <u>Description</u>

2-1-1 Required back-up lights do not function.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.