## **REPORT OF SCHOOL BUS INSPECTION**

| Type of<br>Inspection: | Annual            |            | D         | )ate:            | 6/26/2015      | Time:                 | 10:47 AM |
|------------------------|-------------------|------------|-----------|------------------|----------------|-----------------------|----------|
| Name of School Co      | orporation:       | EASTERN PL | JLASKI CO | OMM SCH CORP     |                | Corp ID:              | 666620   |
| Address of School      | Corporation:      | 711 Sch    | nool Dr   |                  |                |                       |          |
| City:                  | Winamac           | Zip:       | 46        | 6996             |                | <b>County Number:</b> | 66       |
| VIN:                   | 4DRBUSKP9         | 3B334307   | Li        | icense Number:   | 74499          | Bus Number:           | 14       |
| Make of Body:          | IC<br>Corporation | Year: 2011 | М         | lake of Chassis: | IC Corporation | Year:                 | 2011     |
| Bus Type:              | С                 |            | М         | lileage:         | 28098          |                       |          |
| Inspection Status:     | R                 | Inspect    | ted By: N | lathan Sherer    |                | PE:                   | 7029     |

**Violations - Rejected** 

Inspection CodeDescription90-1-3The strobe light is inoperative

Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.