

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	6/30/2015	Time:	9:05 AM
Name of School Corporation:	ST JOHN LUTHERAN SCHOOL (57)	Corp ID:	220024		
Address of School Corporation:	301 S Oak Street				
City:	Kendallville	Zip:	46755	County Number:	57
VIN:	1GBHG31V541195656	License Number:	B826A	Bus Number:	1
Make of Body:	Collins Bus Corporation	Year:	2004	Make of Chassis:	Chevrolet
Bus Type:	A1	Mileage:	41833		
Inspection Status:	O	Inspected By:	Brian Bills	PE:	5506

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-2	Tires with visible bumps, bulges, or knots indicating partial failure or separation of the tire structure

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.