REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/10/2015	**Time:**	9:59 AM
Name of School Corporation:	CULVER COMMUNITY SCHOOLS CORP.			**Corp ID:**	505455
Address of School Corporation:	PO Box 231				
City:	Culver	**Zip:**	46511	**County Number:**	50
VIN:	4DRBUSKP7BB338453	**License Number:**	16716	**Bus Number:**	28
Make of Body:	IC Corporation **Year:** 2011	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	C	**Mileage:**	94371		
Inspection Status:	R	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.