REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	7/6/2015	**Time:**	1:34 PM
Name of School Corporation:	SOUTH HARRISON COMM. SCH. CORP			**Corp ID:**	313190
Address of School Corporation:	315 S Harrison Dr				
City:	Corydon	**Zip:**	47112	**County Number:**	31
VIN:	1HVBRABPX1A936518	**License Number:**	E465303	**Bus Number:**	31
Make of Body:	AmTran **Year:** 2001	**Make of Chassis:**	IC Corporation	**Year:**	2001
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Troy Boyd	**PE:**	5171

Violations - Rejected

Inspection Code	Description
15-1-1	The defroster system is not working properly.

Violations - Out of Service

Inspection Code	Description
8-2-1	There is no brake certification, or the certification has expired or is not signed
59-2-4	Stop arm does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.