## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	7/9/2015	Time:	11:56 AM
Name of School Co	•	SOU		COMM. SCH. CO	RP	Corp ID:	313190
Address of School	Corporation:		315 S Harrison	n Dr			
City:	Corydon		Zip:	47112		County Number:	31
VIN:	1GBL7T1C6XJ10626	68		License Number:	B812G	Bus Number:	13
Make of Body:	Blue Bird Corporation	Year:	2000	Make of Chassis:	Chevrolet	Year:	2000
Bus Type:	С			Mileage:	Unknown		
Inspection Status:	R		Inspected By:	Troy Boyd		PE:	5171

## Violations - Rejected

Inspection Code	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
64-1-4	Any front turn signal does not function properly

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.