

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/15/2015	Time:	10:44 AM
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750
Address of School Corporation:	2 S 3rd St.				
City:	Flora	Zip:	46929	County Number:	8
VIN:	4DRBUAAP7CB590782	License Number:	3628	Bus Number:	17
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	60975	Year:	2012
Inspection Status:	O	Inspected By:	Nate King	PE:	7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-5	Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent major grooves

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.