

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/15/2015	Time:	11:30 AM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	1BAKFCPH6AF271304		License Number:	72275	Bus Number:	6	
Make of Body:	Blue Bird Corporation	Year:	2010	Make of Chassis:	Blue Bird Corporation	Year:	2010
Bus Type:	C			Mileage:	75524		
Inspection Status:	O	Inspected By:	Nate King	PE:	7421		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
22-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.