

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/15/2015	Time:	1:46 PM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	1FDWE35F13HB85204		License Number:	66833	Bus Number:	2sb	
Make of Body:	Mid Bus, Inc.	Year:	2003	Make of Chassis:	Ford	Year:	2003
Bus Type:			Mileage:	92034			
Inspection Status:	O	Inspected By:	Nate King	PE:	7421		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (1/2) inch in diameter.

Bus Type Description