

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 7/15/2015	Time: 1:46 PM
Name of School Corporation: CARROLL CONS. SCHOOL CORP.	Corp ID: 80750	
Address of School Corporation: 2 S 3rd St.		
City: Flora	Zip: 46929	County Number: 8
VIN: 1FDWE35F13HB85204	License Number: 66833	Bus Number: 2sb
Make of Body: Mid Bus, Inc. Year: 2003	Make of Chassis: Ford	Year: 2003
Bus Type:	Mileage: 92034	
Inspection Status: <input type="radio"/>	Inspected By: Nate King	PE: 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (\hat{A} ½) inch in diameter.

Bus Type Description