# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | | **Date:** | 7/15/2015 | **Time:** | 1:55 PM |
| **Name of School Corporation:** | CARROLL CONS. SCHOOL CORP. | | | | **Corp ID:** | 80750 |
| **Address of School Corporation:** | 2 S 3rd St. | | | | | |
| **City:** | Flora | **Zip:** | 46929 | | **County Number:** | 8 |
| **VIN:** | 1GB3G2BL3E1174467 | | **License Number:** | 26781 | **Bus Number:** | 5sb |
| **Make of Body:** | Starcraft **Year:** | 2014 | **Make of Chassis:** | Starcraft | **Year:** | 2014 |
| **Bus Type:** | | | **Mileage:** | 11996 | | |
| **Inspection Status:** | A | **Inspected By:** | Nate King | | **PE:** | 7421 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

| Bus Type Description |
|---|