REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: RegistrationDate:7/21/2015Time:8:40 AMName of School Corporation:CULVER COMMUNITY SCHOOLS CORP.Corp ID:505455

Address of School Corporation: PO Box 231

City:CulverZip:46511County Number:50VIN:4DRBUC8P1GB192121License Number:11939Bus Number:19Make of Body:IC Corporation Year:2016Make of Chassis:IC Corporation Year:2016

Bus Type: C Mileage: 972

Inspection Status: O Inspected By: Travis Harrold PE: 8022

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

Warning lights fail to operate correctly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.