

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                       |                        |              |                         |                       |
|---------------------------------------|-----------------------|------------------------|--------------|-------------------------|-----------------------|
| <b>Type of Inspection:</b>            | Registration          | <b>Date:</b>           | 7/29/2015    | <b>Time:</b>            | 10:15 AM              |
| <b>Name of School Corporation:</b>    | TRI-CENTRAL SCHOOLS   | <b>Corp ID:</b>        |              |                         | 807935                |
| <b>Address of School Corporation:</b> | 2115 W 500 N          |                        |              |                         |                       |
| <b>City:</b>                          | Sharpsville           | <b>Zip:</b>            | 46068        | <b>County Number:</b>   | 80                    |
| <b>VIN:</b>                           | 4DRBBAAP33B581664     | <b>License Number:</b> | B808B        | <b>Bus Number:</b>      | 2                     |
| <b>Make of Body:</b>                  | Blue Bird Corporation | <b>Year:</b>           | 2003         | <b>Make of Chassis:</b> | Blue Bird Corporation |
| <b>Bus Type:</b>                      | C                     | <b>Mileage:</b>        | 88800        | <b>Year:</b>            | 2003                  |
| <b>Inspection Status:</b>             | O                     | <b>Inspected By:</b>   | Randy McPike | <b>PE:</b>              | 7018                  |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code Description

50-2-1      There is no seat belt cutter in the vehicle

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**