

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------------|------------------------|------------------|-------------------------|--------------|--------------|------|
| Type of Inspection: | Annual | Date: | 7/29/2015 | Time: | 8:37 AM | | |
| Name of School Corporation: | AVON COMMUNITY SCHOOLS | | | Corp ID: | 323315 | | |
| Address of School Corporation: | 7203 E HWY 36 | | | | | | |
| City: | Avon | Zip: | 46123 | County Number: | 32 | | |
| VIN: | 4UZAAXAL42CJ46255 | License Number: | 18207 | Bus Number: | 71 | | |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2002 | Make of Chassis: | Freightliner | Year: | 2002 |
| Bus Type: | C | Mileage: | 141886 | | | | |
| Inspection Status: | A | Inspected By: | Larry Gershanoff | PE: | 4417 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.