## REPORT OF SCHOOL BUS INSPECTION

Type of 10:29 Re-Inspection 7/29/2015 **Time**: Date: Inspection: AM Name of School Corporation: **AVON COMMUNITY SCHOOLS** Corp ID: 323315 7203 E HWY 36 **Address of School Corporation:** County City: Avon Zip: 46123 32 Number: License VIN: 4UZAAXDC65CN93640 20402 **Bus Number:** 113 Number: Make of Thomas Built Buses, Year: 2005 Freightliner Year: 2005 Make of Body: Inc. Chassis: **Bus Type:** С Mileage: 16910 Inspection Inspected R PE: Larry Gershanoff 4417 Status: By:

## **Violations - Rejected**

<u>Inspection Code</u> <u>Description</u>

7-1-3 Air leak at proper connection

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.