REPORT OF SCHOOL BUS INSPECTION

Type of 9:55 Registration Date: 7/30/2015 **Time**: Inspection: AM Name of School Corporation: HOLY TRINITY CATHOLIC SCHOOL 19A865 Corp ID: **Address of School Corporation:** 990 Church Ave County City: Jasper Zip: 47546 19 Number: License VIN: 1BABKCPA68F250641 B870K **Bus Number:** 3 Number: Make of Blue Bird Year: 2008 Make of Body: Freightliner Year: 2008 Corporation Chassis: **Bus Type:** С Mileage: 49989 Inspected Mike Adams PE: **Inspection Status:** O 7407 By:

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

7-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.