## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Re-Inspection		Date:	8/4/2015	Time:	10:23 AM
Name of School Co	orporation: CAR	ROLL CONS. S	CHOOL CORP.		Corp ID:	80750
Address of School	Corporation:	2 S 3rd St.				
City:	Flora	Zip:	46929		<b>County Number:</b>	8
VIN:	1FDWE35F13HB8	5204	License Number:	66833	Bus Number:	2sb
Make of Body:	Mid Bus, Inc. Year:	2003	Make of Chassis:	Ford	Year:	2003
Bus Type:			Mileage:	92034		
Inspection Status:	А	Inspected By:	Nate King		PE:	7421

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

**Bus Type Description**