

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 8/4/2015 **Time:** 10:23 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP. **Corp ID:** 80750
Address of School Corporation: 2 S 3rd St.
City: Flora **Zip:** 46929 **County Number:** 8
VIN: 1FDWE35F13HB85204 **License Number:** 66833 **Bus Number:** 2sb
Make of Body: Mid Bus, Inc. **Year:** 2003 **Make of Chassis:** Ford **Year:** 2003
Bus Type: **Mileage:** 92034
Inspection Status: A **Inspected By:** Nate King **PE:** 7421

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description