

## REPORT OF SCHOOL BUS INSPECTION

|   |                                  |   |
|---|----------------------------------|---|
| <b>Type of Inspection:</b> Annual                                 | <b>Date:</b> 8/21/2015           | <b>Time:</b> 8:45 AM                          |
| <b>Name of School Corporation:</b> ST JOSEPH CATHOLIC SCHOOL (17) | <b>Corp ID:</b> 17A735           |   |
| <b>Address of School Corporation:</b> 300 W Houston Street        |                                  |   |
| <b>City:</b> Garrett  | <b>Zip:</b> 46738                | <b>County Number:</b> 17                      |
| <b>VIN:</b> 1GDG7T1C6YJ526364                                     | <b>License Number:</b> B802B     | <b>Bus Number:</b> 2                          |
| <b>Make of Body:</b> Blue Bird Corporation                        | <b>Year:</b> 2000                | <b>Make of Chassis:</b> Blue Bird Corporation |
| <b>Bus Type:</b> C  | <b>Mileage:</b> 315747           | <b>Year:</b> 2000                             |
| <b>Inspection Status:</b> O                                       | <b>Inspected By:</b> Eric Egbert | <b>PE:</b> 7006                               |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 22-1-1                 | A dripping oil or fluid leak   |
| 62-1-2                 | One (1) taillight or one (1) brake light does not function   |
| 28-1-4                 | The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction. |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 8-2-1                  | There is no brake certification, or the certification has expired or is not signed |

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.