

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/25/2015	Time:	9:26 AM
Name of School Corporation:	EAST NOBLE SCHOOL CORPORATION			Corp ID:	576060
Address of School Corporation:	126 W Rush St				
City:	Kendallville	Zip:	46755	County Number:	57
VIN:	4DRBUSKN99B681659	License Number:	31509	Bus Number:	41
Make of Body:	IC Corporation	Year:	2009	Make of Chassis:	IC Corporation
Year:	2009	Mileage:	100677	PE:	5506
Bus Type:	C	Inspected By:	Brian Bills		
Inspection Status:	O				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
51-1-1	Any door seals are missing, damaged, or torn
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent
51-2-1	The service door does not open or close properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.