

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/3/2015	Time:	8:30 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	Zip:	47529	County Number:	14
VIN:	4DRBBAAP63B581643	License Number:	B891D	Bus Number:	7
Make of Body:	Blue Bird Corporation	Year:	2003	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	126355	Year:	2003
Inspection Status:	R	Inspected By:	Mike Adams	PE:	7407

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
53-1-1	One (1) leaf spring is broken under the first two (2) leaves
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.