REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		**Date:** 9/3/2015	**Time:**	8:30 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	4DRBBAAP63B581643		**License Number:** B891D	**Bus Number:**	7
Make of Body:	Blue Bird Corporation	**Year:** 2003	**Make of Chassis:** IC Corporation	**Year:**	2003
Bus Type:	C		**Mileage:** 126355		
Inspection Status:	R	**Inspected By:**	Mike Adams	**PE:**	7407

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
53-1-1	One (1) leaf spring is broken under the first two (2) leaves
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.