

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/4/2015	Time:	10:20 AM
Name of School Corporation:	SOUTH BEND COMM. SCHOOL CORP.	Corp ID:	717205		
Address of School Corporation:	3003 N Bendix Dr				
City:	South Bend	Zip:	46601	County Number:	71
VIN:	4DRBUAAN88B493824	License Number:	31248	Bus Number:	195
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation
Year:	2008	Year:	2008		
Bus Type:	C	Mileage:	133747		
Inspection Status:	O	Inspected By:	Travis Harrold	PE:	8022

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.