

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 9/22/2015	<b>Time:</b> 9:11 AM
<b>Name of School Corporation:</b> NORTH GIBSON SCHOOL CORP.	<b>Corp ID:</b> 262735	
<b>Address of School Corporation:</b> 1108 N Embree St		
<b>City:</b> Princeton	<b>Zip:</b> 47670	<b>County Number:</b> 26
<b>VIN:</b> 4DRBWAAR95A983509	<b>License Number:</b> 20791	<b>Bus Number:</b> 56
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2005	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2005	<b>Mileage:</b> 79505	<b>Year:</b> 2005
<b>Bus Type:</b> D		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Bradley Miller	<b>PE:</b> 7809

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-2	The headlight dimmer switch fails to operate properly
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
55-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure)
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**