

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	10/1/2015	<b>Time:</b>	10:28 AM
<b>Name of School Corporation:</b>	M.S.D. MARTINSVILLE SCHOOLS			<b>Corp ID:</b>	555925
<b>Address of School Corporation:</b>	PO Box 1416				
<b>City:</b>	Martinsville	<b>Zip:</b>	46151	<b>County Number:</b>	55
<b>VIN:</b>	4UZABRDJX8CZ10850	<b>License Number:</b>	B766G	<b>Bus Number:</b>	12
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	106675	<b>Year:</b>	2008
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Mike Adams	<b>PE:</b>	7407

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
53-2-3	Coil springs, torque rods or torsion bars are broken or missing
82-2-1	No OOS criteria
67-2-1	Rim or wheel discs have visible cracks, elongated bolt holes or any indication of repair by welding

#### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**