

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	Date:	10/19/2015	Time:	11:46 AM
Name of School Corporation:	DECATUR COUNTY COMM. SCHOOL			Corp ID:	161655
Address of School Corporation:	1645 W SR 46				
City:	Greensburg	Zip:	47240	County Number:	16
VIN:	1HVBBABP3SH686570	License Number:	B786C	Bus Number:	12
Make of Body:	Thomas Built Buses, Inc.	Year:	1995	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	177020	Year:	1995
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-1	The bus body has rust or rusted through areas which may weaken the body
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.