

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/20/2015 **Time:** 8:30 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP **Corp ID:** 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo **Zip:** 47140 **County Number:** 13
VIN: 1GBL7T1C9XJ106717 **License Number:** B287f **Bus Number:** 31
Make of Body: Chevrolet **Year:** 2000 **Make of Chassis:** Chevrolet **Year:** 2000
Bus Type: C **Mileage:** 188668
Inspection Status: R **Inspected By:** Mark Raper **PE:** 6473

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
46-1-2	Any seat back or bottom is loose
62-1-1	Any lens is cracked, missing, faded or of the wrong color

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.