## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 10/20/2015 Time: 8:30 AM

Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1GBL7T1C9XJ106717License Number:Bus Number:31Make of Body:Chevrolet Year:2000Make of Chassis:Chevrolet Year:2000

Bus Type: C Mileage: 188668

Inspection Status: R Inspected By: Mark Raper PE: 6473

## Violations - Rejected

## Inspection CodeDescription41-1-4There is debris in the bus. (needs cleaned/includes dirt)46-1-2Any seat back or bottom is loose62-1-1Any lens is cracked, missing, faded or of the wrong color

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.