

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/19/2015 **Time:** 8:48 AM
Name of School Corporation: ELWOOD COMMUNITY SCHOOL CORP. **Corp ID:** 485280
Address of School Corporation: 1306 N Anderson St
City: Elwood **Zip:** 46036 **County Number:** 48
VIN: 1GDHG31F3X1065346 **License Number:** 25960 **Bus Number:** A1
Make of Body: Corbeil **Year:** 1999 **Make of Chassis:** GMC **Year:** 1999
Bus Type: **Mileage:** 50333
Inspection Status: R **Inspected By:** Jeremy Mason **PE:** 8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description