## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Semi-Annual		Date:	10/20/2015	Time:	8:22 AM
Name of School Co	orporation: CEN	FERVILLE-ABIN	IGTON COMM SCH	IS	Corp ID:	898360
Address of School Corporation: 116 W SOUTH ST						
City:	CENTERVILLE	Zip:	47330		County Number:	89
VIN:	1HUBBABNGYH283	626	License Number:	17801	Bus Number:	18
Make of Body:	IC Corporation Year:	2000	Make of Chassis:	AmTran	Year:	2000
Bus Type:	С		Mileage:	89415		
Inspection Status:	R	Inspected By:	Jeremy Mason		PE:	8139

## **Violations - Rejected**

Inspection <u>Code</u>	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
48-1-1	Power steering unit leaks at any point

## Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.