

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------|------------------------|------------|-------------------------|----------------|--------------|------|
| Type of Inspection: | Semi-Annual | Date: | 10/20/2015 | Time: | 9:30 AM | | |
| Name of School Corporation: | BROWN CO SCH CORP | Corp ID: | 70670 | | | | |
| Address of School Corporation: | 150 SCHOOLHOUSE LN | | | | | | |
| City: | Nashville | Zip: | 47448 | County Number: | 7 | | |
| VIN: | 4DRBRAAP93B952063 | License Number: | B623F | Bus Number: | 28 | | |
| Make of Body: | IC Corporation | Year: | 2003 | Make of Chassis: | IC Corporation | Year: | 2003 |
| Bus Type: | C | Mileage: | 140884 | | | | |
| Inspection Status: | R | Inspected By: | Mark Raper | PE: | 6473 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 20-1-2 | Excessive effort is needed to open the emergency door |
| 23-1-2 | Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted) |
| 63-1-4 | Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves |
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.