REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 10/20/2015 **Time**: 8:22 AM 898360

Name of School Corporation: CENTERVILLE-ABINGTON COMM SCHS Corp ID:

Address of School Corporation: 116 W SOUTH ST

47330 City: **CENTERVILLE** Zip: County Number: 89 VIN: **Bus Number:** 1HUBBABNGYH283626 License Number: 17801 18 Make of Body: Make of Chassis: AmTran 2000 IC Corporation Year: 2000 Year:

Bus Type: C Mileage: 89415

PE: **Inspection Status:** R Inspected By: Jeremy Mason 8139

Violations - Rejected

<u>Inspection</u> **Description** Code

48-1-1 Power steering unit leaks at any point

The bus body has loose, damaged or improperly aligned body parts. These would 24-1-2 include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code Description</u>

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.