## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:10/20/2015 Time:8:59 AM

Name of School Corporation: CENTERVILLE-ABINGTON COMM SCHS Corp ID: 898360

Address of School Corporation: 116 W SOUTH ST

City:CENTERVILLEZip:47330County Number:89VIN:1GDHG31F7X1065236License Number:50484Bus Number:A3Make of Body:GMCYear:1999Make of Chassis:CorbeilYear:1999

Bus Type: Mileage: 121402

Inspection Status: A Inspected By: Jeremy Mason PE: 8139

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**