

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual	Date: 11/10/2015	Time: 9:11 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP	Corp ID: 131300	
Address of School Corporation: 5808 E Administration Rd		
City: Marengo	Zip: 47140	County Number: 13
VIN: 1HVBBABP8XH208703	License Number: B619E	Bus Number: 1
Make of Body: IC Corporation	Year: 1999	Make of Chassis: IC Corporation
Year: 1999	Mileage: 129897	Year: 1999
Bus Type: C		
Inspection Status: O	Inspected By: Travis Coryea	PE: 5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
65-1-1	Any lens is cracked, broken or discolored

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
65-2-1	Warning lights fail to operate correctly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.