REPORT OF SCHOOL BUS INSPECTION

Type of Spot Checks Date: 10/16/2015 Time: 10:06 AM

Name of School Corporation: CULVER COMMUNITY SCHOOLS CORP. Corp ID: 505455

Address of School Corporation: PO Box 231

City: Culver Zip: 46511 County Number: 50
VIN: 4DRBUSKP0AB182075 License Number: 2486 Bus Number: 10
Make of Body: Comparation Year: 2010 Make of Chassis: IC Corporation Year: 2010

Bus Type: C Mileage: 58564

Inspection Status: O Inspected By: Brian Bills PE: 5506

Violations - Rejected

Inspection Code Description

Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent

major grooves

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.