

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	Date:	10/16/2015	Time:	10:06 AM		
Name of School Corporation:	CULVER COMMUNITY SCHOOLS CORP.			Corp ID:	505455		
Address of School Corporation:	PO Box 231						
City:	Culver	Zip:	46511	County Number:	50		
VIN:	4DRBUSKP0AB182075		License Number:	2486	Bus Number:	10	
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation	Year:	2010
Bus Type:	C			Mileage:	58564		
Inspection Status:	O	Inspected By:	Brian Bills	PE:	5506		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.