REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	11/13/2015	**Time:**	11:39 AM
Name of School Corporation:	FRANKTON-LAPEL COMM. SCHLS.			**Corp ID:**	485245
Address of School Corporation:	7916 W 300 N				
City:	Anderson	**Zip:**	46011	**County Number:**	48
VIN:	1GB6G3AG6A1169586	**License Number:**	4241	**Bus Number:**	A7
Make of Body:	Girardin Minibus, Inc. **Year:** 2010	**Make of Chassis:**	Chevrolet	**Year:**	2010
Bus Type:		**Mileage:**	31340		
Inspection Status:	A	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description

Bus Type	Description