

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/20/2015	Time:	8:47 AM
Name of School Corporation:	PERU COMMUNITY SCHOOLS	Corp ID:	525635		
Address of School Corporation:	35 W 3rd St				
City:	Peru	Zip:	46970	County Number:	52
VIN:	1T7HT4B22X1068534	License Number:	1725	Bus Number:	21
Make of Body:	Thomas Built Buses, Inc.	Year:	1999	Make of Chassis:	Freightliner
Bus Type:	D	Mileage:	147468		
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-3	Any required padding is missing
3-1-4	Battery terminals are excessively corroded

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.