

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/20/2015	Time:	9:15 AM
Name of School Corporation:	PERU COMMUNITY SCHOOLS			Corp ID:	525635
Address of School Corporation:	35 W 3rd St				
City:	Peru	Zip:	46970	County Number:	52
VIN:	1HVBBABP8TH372818	License Number:	15298	Bus Number:	9
Make of Body:	Thomas Built Buses, Inc.	Year:	1997	Make of Chassis:	IC Corporation
Year:	1997	Mileage:	143239	PE:	7018
Bus Type:	C	Inspected By:	Randy McPike		
Inspection Status:	O				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-2	Any crossmember is rusted sufficiently to weaken floor supports

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.