

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/20/2015	Time:	9:43 AM		
Name of School Corporation:	PERU COMMUNITY SCHOOLS			Corp ID:	525635		
Address of School Corporation:	35 W 3rd St						
City:	Peru	Zip:	46970	County Number:	52		
VIN:	4UZ6CFAA7XCB78748		License Number:	15297	Bus Number:	8	
Make of Body:	Thomas Built Buses, Inc.	Year:	1999	Make of Chassis:	Freightliner	Year:	1999
Bus Type:	C			Mileage:	149597		
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-2	Any shock absorber is leaking fluid
70-1-9	If the words "EMERGENCY EXIT" does not appear directly above each emergency exit window on the inside of the bus

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.