REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-AnnualDate:12/9/2015Time:8:58 AMName of School Corporation:BAUGO COMMUNITY SCHOOLSCorp ID:202260

Address of School Corporation: 29125 CR 22 W

City:ElkhartZip:46517County Number: 20VIN:1BAAHCPA31F097359License Number: B792GBus Number: 12Make of Body:Blue Bird Corporation Year: 2001Make of Chassis: Blue Bird Corporation Year: 2001

Bus Type: D Mileage: 141054

Inspection Status: R Inspected By: Brian Bills PE: 5506

Violations - Rejected

Inspection Code	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.