REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 12/15/2015 Time: 9:37 AM

Name of School Corporation: CARROLL CONS. SCHOOL CORP.

Corp ID: 80750

Address of School Corporation: 2 S 3rd St.

City:FloraZip:46929County Number:8VIN:1FDWE35F13HB85204License Number:66833Bus Number:2sbMake of Body:Mid Bus, Inc. Year:2003Make of Chassis:FordYear:2003

Bus Type: Mileage: 94329

Inspection Status: R Inspected By: Nate King PE: 7421

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

16-1-1 There are any leaks from the differential, pinion seal, or either rear wheel seal

Violations - Out of Service

Inspection Code Description

Bus Type Description