

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |             |                         |                          |
|---------------------------------------|--------------------------------|------------------------|-------------|-------------------------|--------------------------|
| <b>Type of Inspection:</b>            | Semi-Annual                    | <b>Date:</b>           | 12/15/2015  | <b>Time:</b>            | 1:43 PM                  |
| <b>Name of School Corporation:</b>    | SOUTH DEARBORN COMM. SCH. CORP |                        |             | <b>Corp ID:</b>         | 151600                   |
| <b>Address of School Corporation:</b> | 6109 Squire Place              |                        |             |                         |                          |
| <b>City:</b>                          | Aurora                         | <b>Zip:</b>            | 47001       | <b>County Number:</b>   | 15                       |
| <b>VIN:</b>                           | 1T88R3B10Y1082106              | <b>License Number:</b> | B591C       | <b>Bus Number:</b>      | 17                       |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.       | <b>Year:</b>           | 2000        | <b>Make of Chassis:</b> | Thomas Built Buses, Inc. |
| <b>Bus Type:</b>                      | B                              | <b>Mileage:</b>        | 77234       | <b>Year:</b>            | 2000                     |
| <b>Inspection Status:</b>             | A                              | <b>Inspected By:</b>   | Chris Clark | <b>PE:</b>              | 6665                     |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**