## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:12/15/2015 Time:3:53 PM

Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750

Address of School Corporation: 2 S 3rd St.

City:FloraZip:46929County Number:8VIN:1FDWE35F13HB85204License Number:66833Bus Number:2sbMake of Body:Mid Bus, Inc. Year:2003Make of Chassis:FordYear:2003

Bus Type: Mileage: 94329

Inspection Status: A Inspected By: Nate King PE: 7421

Violations - Rejected

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**