

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|--------------------------------|-----------------------|-------------|------------------|----------------|
| Type of Inspection: | Semi-Annual | Date: | 12/29/2015 | Time: | 9:52 AM |
| Name of School Corporation: | SOUTH DEARBORN COMM. SCH. CORP | | | Corp ID: | 151600 |
| Address of School Corporation: | 6109 Squire Place | | | | |
| City: | Aurora | Zip: | 47001 | County Number: | 15 |
| VIN: | 1GDHG31R111105540 | License Number: B163D | | | Bus Number: 44 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2001 | Make of Chassis: | GMC |
| Bus Type: | Mileage: 155068 | | | | |
| Inspection Status: | A | Inspected By: | Chris Clark | PE: | 6665 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description