

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/11/2016	Time:	11:11 AM
Name of School Corporation:	JOHN GLENN SCHOOL CORPORATION			Corp ID:	717150
Address of School Corporation:	101 John Glen Dr				
City:	Walkerton	Zip:	46574	County Number:	71
VIN:	4UZABRDJX8CZ10895	License Number:	30499	Bus Number:	26
Make of Body:	Thomas Built Buses, Inc.	Year:	2008	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C			Mileage:	77868
Inspection Status:	O	Inspected By:	Travis Harrold	PE:	8022

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
34-1-1	Any headlight is inoperative
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
64-2-1	Any rear turn signal does not function properly
65-2-1	Warning lights fail to operate correctly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.