

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|--------------------------------|-------------------------------|-----------------|----------------|------------------|--------------------------|-------|------|
| Type of Inspection: | Post-Crash Inspection | Date: | 1/11/2016 | Time: | 11:26 AM | | |
| Name of School Corporation: | JOHN GLENN SCHOOL CORPORATION | | | Corp ID: | 717150 | | |
| Address of School Corporation: | 101 John Glen Dr | | | | | | |
| City: | Walkerton | Zip: | 46574 | County Number: | 71 | | |
| VIN: | 4UZABRDJX8CZ10895 | License Number: | 30499 | Bus Number: | 26 | | |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2008 | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2008 |
| Bus Type: | C | Mileage: | 77868 | | | | |
| Inspection Status: | O | Inspected By: | Travis Harrold | PE: | 8022 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 34-1-1 | Any headlight is inoperative |
| 11-1-2 | The front or rear bumper is not properly attached, missing, torn, loose, or altered. |
| 64-1-4 | Any front turn signal does not function properly |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 65-2-1 | Warning lights fail to operate correctly |
| 7-2-1 | There is no brake certification form the certification is expired or is not signed within the six-month requirement |
| 64-2-1 | Any rear turn signal does not function properly |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.