

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/14/2016	Time:	9:14 AM		
Name of School Corporation:	M.S.D. LAWRENCE TOWNSHIP			Corp ID:	495330		
Address of School Corporation:	5850 Thunderbird Rd						
City:	Indianapolis	Zip:	46236	County Number:	49		
VIN:	4DRBWAAR7CB378511		License Number:	227	Bus Number:	5	
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2012
Bus Type:	D			Mileage:	57453		
Inspection Status:	O	Inspected By:	Larry Gershonoff	PE:	4417		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
64-1-2	A lens is cracked, missing or wrong color

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
51-2-1	The service door does not open or close properly
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
59-2-5	There are no OOS criteria for the optional school bus crossing arm

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.