

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	1/26/2016	<b>Time:</b>	10:24 AM
<b>Name of School Corporation:</b>	GREATER CLARK CO SCHLS			<b>Corp ID:</b>	101010
<b>Address of School Corporation:</b>	301 E 11th St				
<b>City:</b>	Jeffersonville	<b>Zip:</b>	47130	<b>County Number:</b>	10
<b>VIN:</b>	1HVBBAAP53H556468	<b>License Number:</b>	NEW1C	<b>Bus Number:</b>	1C
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2003	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	124013	<b>Year:</b>	2003
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Troy Boyd	<b>PE:</b>	5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**